#### IN THE UNITED STATES PATENT AND TRADEMARK OFFICE

In re Patent of

U.S. Patent No. : 6.938.933 B2 Issued : September 6, 2005

Title : CORRUGATED PLASTIC PIPE SECTIONS HAVING FLANGED

ENDS AND STRUCTURALLY TIGHT JOINTS THEREOF

Docket No. : 3994648-129160/CPP 0002 NA/33640.3

Certificate of Corrections Branch

EFS Web Electronic Submission Commissioner for Patents March 29, 2007

P.O. Box 1450

Alexandria, VA 22313-1450

Sir

## REQUEST FOR CERTIFICATE OF CORRECTION FOR PTO MISTAKE UNDER 35 U.S.C. 254 and 37 C.F.R. 1.322

In the matter of U.S. Patent No. 6,938,933 B2, it is respectfully requested that a Certificate of Correction be issued to cover the following errors which occurred in the printing of the patent.

Column 13, Line 17 "of the damp" should read -- of the clamp --;

Column 13, Line 17 "when the damp" should read --when the clamp--:

Column 14, Line 41 "alone" should read --along--; and

Column 14, Line 47 "oboe" should read --pipe--.

### REMARKS

It is respectfully requested that a Certificate of Correction be issued for the above-identified patent. All of the above errors occurred during the printing of the patent and, therefore, no fee is due. A copy of the required Certificate of Correction Form PTO/SB/44 is attached.

# Respectfully submitted,

## DINSMORE & SHOHL LLP

By <u>/Richard A. Killworth/</u> Richard A. Killworth Registration No. 26,397

One Dayton Centre One South Main St., Suite 1300 Dayton, Ohio 45402-2023 Telephone: (937) 449-6400 Facsimile: (937) 449-6405

RAK/tlo Encl.

Page \_\_1\_ of \_\_1

Approved for use through 04/30/2007, OMB 0651-0033 U.S. Patent and Trademark Office: U.S. DEPARTMENT OF COMMERCE

Under the Paperwork Reduction Act of 1995, no persons are required to respond to a collection of information unless it displays a valid OMB control number. (Also Form PTO-1050)

## UNITED STATES PATENT AND TRADEMARK OFFICE CERTIFICATE OF CORRECTION

PATENT NO. : 6,938,933 B2	
APPLICATION NO.: 10/698,601	
ISSUE DATE : September 6, 2005	
INVENTOR(S) : Starita	
It is certified that an error appears or errors appear in the above-identified patent and that said L is hereby corrected as shown below:	etters Patent.
Column 13, Line 17 "of the damp" should readof the clamp;	
Column 13, Line 17 "when the damp" should readwhen the clamp;	
Column 14, Line 41 "alone" should readalong; and	
Column 14, Line 47 "oboe" should readpipe	

MAILING ADDRESS OF SENDER (Please do not use customer number below):

Dinsmore & Shohl, LLP

One Dayton Centre

One South Main Street, Suite 1300

Dayton, Ohio 45402

This collection of information is required by 37 CFR 1.322, 1.323, and 1.324. The information is required to obtain or retain a benefit by the public which is to file (and by the USPTO to process) an application. Confidentiality is governed by 35 U.S.C. 122 and 37 CFR 1.14. This collection is estimated to take 1.0 hour to complete, including gathering, preparing, and submitting the completed application form to the USPTO. Time will vary depending upon the individual case. Any comments on the amount of time you require to complete this form and/or suggestions for reducing this burden, should be sent to the Chief Information Officer, U.S. Patent and Trademark Office, U.S. Department of Commerce, P.O. Box 1450, Alexandria, VA 22313-1450. DO NOT SEND FEES OR COMPLETED FORMS TO THIS ADDRESS. SEND TO: Attention Certificate of Corrections Branch. Commissioner for Patents. P.O. Box 1450. Alexandria. VA 22313-1450.